




Kabelbaum zum Oberteil

Cable tree to sewing head

Faisceau de câbles vers la tête de machine

Mazo de cables para el cabezal

PFAFF 1053-900/24

PFAFF 1183-900/24

12.02

